

Arecibo Inspection Photo Album

April 22, 2008

by Carl F. Plössl



Entrance to Landfill (right) and Natural Reserve (left)























TANQUE
ACEITE US

































































Operating face. Note: use of both 'dozers and landfill compactors (better compaction).



Exposed trash in non-active areas indicates areas of poor daily cover or eroded cover. Also, windblown trash.



Operating face. Note: ponding.



Exposed trash in non-active areas indicates areas of poor daily cover or eroded cover.



Scrap metal recovery operations from off-site (road is along property line—landfill is to the right).



Scrap metal recovery operations from off-site (road is along property line—landfill is to the right).